

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:						
Company	Gary E. Gray Resident Agent					
OGM	Karl Houskeeper Environmental Scientist III					

Inspection Report

Permit Number:	C0070041			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, October 13, 2004			
Start Date/Time:	10/13/2004 9:00:00 AM			
End Date/Time:	10/13/2004 12:00:00 PM			
Last Inspection:	Thursday, September 09, 2004			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp 55 Deg F InspectionID Report Number: 428

Types of Operations

Accepted by: pgrubaug

10/29/2004

Permitee: WEST RIDGE RESOURCES Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Address: PO BOX 1077, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

4,382.55	Total Permitted		
29.06	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

	-	•
✓ Federal		✓ Underground
✓ State		Surface
\square County		Loadout
Fee		Processing
Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending Division Order: Division Order DO00A-7, Extension granted until May 2004. The Division received a response to Division Order DO-00A-7 on June 3, 2004.

Inspector's Signature

Karl

Wednesday, October 13, 2004 Date

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Continuation Sheet

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 13, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		✓	
3.	Topsoil	V		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	~		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 13, 2004

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The SPCC plan needs to be reviewed and updated if needed. The SPCC plan needs to be re-certified by a registered professional engineer in the State of Utah.

2. Signs and Markers

The mine ID signs are located at the pump house and the entrance to the mine site from the county road. The signs contain the permit number, address, and phone number of the operator. Other signs and markers observed during the inspection meet the coal rules.

3. Topsoil

The operator is currently reviewing their records on the topsoil experimental practice site and when the last disturbance was done to the pile to see if the five-year term of the test location has expired. A letter is to be forth coming to the Division to address this issue.

4.a Hydrologic Balance: Diversions

Sediment accumulations are starting to build inside several diversions throughout the mine site from recent storm events. The operator has plans to clean the diversions before the onset of winter.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2004 water monitoring information is in the EDI website and uploaded. Water monitoring is current.

18. Support Facilities, Utility Installations

Two areas where pipelines are located were identified during the previous inspection. The pipelines are not depicted on the surface facilities map. The surface facilities map needs to be updated to show the location and purpose of the pipelines. The operator committed during the last inspection to have the maps updated by the end of the month. During the current inspection, the operator indicated that the drawings for the surface facilities need to be retrieved from taped files by their IT personnel. Once that information is recovered then the maps can be updated and submitted. The information should be submitted to the Division within two weeks. Updating and submitting the surface facilities map to the Division will avoid future enforcement action.